

Imray Correction Notice

IC2100.8

30 August 2012

Chart 2100+8 WGS 84

Edition Nov 2007

Date of printing Nov 2007

The following corrections should be noted:

1 Approaches to Newhaven

Insert spec spher Lt buoy Fl(5)Y.20s in 50°45'·92N 0°04'·40E (ILNW 158/08)

2 Selsey Bill westwards

Insert Y spher Lt buoy Fl(5)Y.20s in 50°43'·38N 0°50'·35W (ILNW 473/08)

3 Selsey southeastwards

Substitute *Bell* for *Whis* at **Owers** Lt buoy in 50°38'·59N 0°41'·09W (ILNW 113/09)

4 Yeoman Points

Yeoman Point 1 should be labeled 50°30'N 00°45'W (ILNW 231/09)

5 Beachy Head

Reduce range of Lt to 8M and delete fog signal Horn(1)30s in 50°44'·02N 0°14'·49E (ILNW 403/10)

6 Brighton southeastwards

Insert dangerous wk sym plus assoc lgd *PA* in 50°48'·02N 0°05'·10W and delete depth 7·4m close by (ILNW 417/10)

7 Newhaven, Friars Bay

Insert R can Lt buoy Q.R in 50°45'·80N 0°00'·44E.

Add outfall pipe from 50°47'·10N 0°01'·22E (shore) to buoy. (ILNW 475/10)

8 Brighton southwards

Insert Wk depth 5m in 50°48'·56N 0°07'·83W (ILNW 256/11)

9 Littlehampton Harbour (Plan B)

Insert minor Lt 2Q.R in 50°48'·29N 0°32'·63W (ILNW 291/11)

10 Littlehampton (Plan A)

Insert minor Lt star Q.R in:

50°48'·40N 0°32'·69W

50°48'·36N 0°32'·65W (ILNW 117/12)

11 Worthing southwards

Insert Lt Mo(U)16m10M Mast(103) (R Lt), plus fog signal Horn Mo(U), in 50°41'·29N 0°20'·59W (ILNW 285/12)

12 Newhaven (Plan C)

Delete Lts Fl.G.5s in:

50°47'·61N 0°03'·20E

50°47'·56N 0°03'·21E

Insert lgd *Works (2012)* close by. (ILNW 357/12)